ZMD-DD-SAN4
Removable Film on ZMD-DD-SAN8 and ZMD-DD-SAN4

If you have received a ZMD-DD-SAN8 or a ZMD-DD-SAN4 and it appears to have a scratch or a scuff on the front panel, please make sure that you have removed the clear protective film on the front of the DVR.

Below you will find a picture showing the clear protective film.



Unique solution ID: #1095
Author: Alex Crewell
Last update: 2013-08-16 20:50

(c) 2026 Jeremy Schultz <itmanager@eptco.com> | 2026-11-24 01:14
URL: https://kb.zmodo.com/index.php?action=artikel&cat=5&id=96&artlang=en