

## ZMD-DD-SAN8

### Removable Film on ZMD-DD-SAN8 and ZMD-DD-SAN4

If you have received a ZMD-DD-SAN8 or a ZMD-DD-SAN4 and it appears to have a scratch or a scuff on the front panel, please make sure that you have removed the clear protective film on the front of the DVR.

Below you will find a picture showing the clear protective film.



Unique solution ID: #1095

Author: Alex Crewell

Last update: 2013-08-16 20:50